PI: Wilson/Lawver			Ph: 614-292-0723 wilson	Cruise #:	MPC: Lowe
Event#: G-099-N			E-mail: twilson@mps.ohio- state.edu	NBP04-01	Date: 02/19/04
Yes	No	Planning	The fact that this was a multi-beam in		
		SIP process adequate?	evident in the SIP. It is hard to explai basically just check boxes. Tere is a section, but you need to be able to conshopping list of equipment should included a large chain dredge was reduced a large by the earlier if he had known the size and whard to use. It is easy to make one more previous pages.	place for comment imment after each lude weight and dir equested, but NSF PI. He could have reight ahead of tim	s at the end of each entry. The mensions of the 's large chain e identified this e. Polar Ice is very
		RSP helpful and timely?	RPSC was very helpful, especially in Dolan had to back out of the cruise, the communicated to the PIs. They would multibeam technician if they had knownew employee.	ne impact of losing d have suggested a	him was not fully a more experienced
		POC responsive?			
		Medical			
		Kits sent out on time?	All kits were sent out on time. The or requested to submit additional information overlooked, delaying his PQ process. delay was, he told them to look into his there, but no one had bothered to real	ation. He did, but a When he called to is file, and the repo	a report was o inquire what the
\boxtimes		Questions answered?	Yes		

1 of 7

Event#: G-099-N			
Date: 2/19/04			
Yes	No	Travel	The form is a little confusing for first-timers.
		TRW available and understandable?	
		Ticketing completed easily?	
		Meet and assist service?	
		Equipment Availability	
		Requested equipment available?	
		Damaged?	The MCS streamer contained a source of 37 Volts that introduced noise into the data. This probably occurred at the manufacturer.
		Late?	
		ECW Gear?	Marine personnel probably do not need as much as is provided in the ECW issue gear.

Event#: G-099-N			
Date: 2/19/04			
Yes	No	Lab Space	
		Adequate? (electrical, space, water, etc.)	The room on this ship spoils you compared to most research vessels.
		Remote Sensing support? (QFax, Terascan, etc.)	Terascan support was great. RadarSat imagery was useless. The whole system needs to be sorted. Dates for receiving images should involve consultation with Pls. At best, dates should not have to be determined far in advance, but images should be received on demand, when need is greatest. If it is necessary to schedule images so early, a list of potential dates should be given to the Pls so that they can choose which two they can be allotted.
		Hotel Services	
		Cabin Assignments?	
		Linens?	Excellent/Lovely
		Food?	Food was ok. There is too much fried food.

Event#:			
Date:			
Yes	No	Personnel Issues	On more than one occasion, a PI was second-guessed by a mate. In one incident, the PI gave specific directions, then returned to the lab to check data. The mate determined alone to change directions and did not consult
		ECO?	the PI before changing the plan. At the turnover between mates, immediate instructions were communicated, but bigger picture plans were not relayed. The scienitsts took over the responsibility of updating mates just after watch change after a few incidences caused confusion.
		RSPC?	RPSC staff was excellent. There were some questions about data processing that couldn't get answered (i.e. magnetic data processing/corrections). There needs to be some documentation on how RPSC gets to the finished product for magnetics and gravity. It was hard to find a person who knows things end-to-end. For example, ETs and ITs each knew one end of a system, but there was no crossover.
		All accomplished? If not, explain (weather, ice, equipment, personnel).	Ice conditions prohibited access to a large portion of the study area (B-15A, B-15K and C-16).

4 of 7

Event#: G-099-N			
Date: 2/19/04			
Yes	No	Surveys Completed?	
		USAP Metrics Survey	The PIs were given the surveys 10-days in advance of the cruise and reminded daily to submit them. They did not, but promised to send them to the POC when they returned home.
		GPRA Facilities Survey	
		If returning for another cruise, are there any additional equipment or support needs your group anticipates?	Magnetic data processing questions need to be answered. The IGRF may be wrong or out of date. There needs to be documentation on processing magnetic and gravity data. The PIs require qualified, experienced multibeam support. Chris Linden did fabulously given the circumstances, but better support was required. The modulator valve on the comporessor needs to be repaires so that changing the demand for air, like at the end of lines, is not such a hassel for the lab and the engine room. Heeling of the ship affected the oil pressure sensor by making it believe it was too low, and it automatically shut down the compressor. This shouldn't happen. The back deck is layed out smartly for seismic deployments, making for smooth equipment transitions. Coring with seismic rails in place is crowded.
		Anything you would like to see changed?	The G/I airguns worked well, and maintenance was great. The solenoid springs need to be addressed. They fail too often. The streamer leveling system worked well. See more on last page

Event#: G-099-N			
Date: 2/19/04			
Yes	No _	Other Diving, Zodiac, E-mail support, interactions with Palmer Station, etc.	There should be an active mouse on the multibeam screen on the bridge. As a new person, it is hard to figure out who to talk to when for seismic deployments. There should be some type of scientist handbook that addresses who to notify and how early each department needs to be notified prior to starting any system. For example, prior to starting seismics, marine mammal observations need to begin in hours. Notify the engine room hours in advance of needing the seismic compressor. etc

Event#: G-099-N

Date: 2/19/04

Additional Comments/Overflow:

MCS Streamer:

We should be able to log the birds.

There were electrical issues in the cable, and RPSC was not prepared to measure leakage to seawater or pair-pair connections.

There is no spare.

There is noise in all of the channels, which is worse during swells. Most lead-ins have stretching capability, and this would probably eliminate the noise.

Depth control was good.

The streamer is not well-balanced, particularly the head and tail.

The Elics should be replaced - the display is useful and flexible, but it is not good enough to tell you if the data are ok. The data it is putting out is mislabeled, which makes it difficult to QC. You have to physically stop acquisition and you can't conveniently do that until the end of a line. The system should log, then massage the data. In this case, the Elics takes data from three sources in a way that doesn't tell you how.

The swath bathymetry system is not suitable for shelf work. The current system is spec'ed for 500 m of water and greater. One rated for shallower water would be more appropriate.

The wiring at the back of the seismic rack is much improved, but still contributes 60 Hz noise that may be prevented by more careful wiring.

There is 100 Hz noise in most of the data, but the source is undetermined. This should be tracked down.

There should be an electrical buffer for trigger signals. The OYO may not have seen and effectively missed some data. This may be why it hangs up when it misses a shot.

outbriefform.pdf (Source Document: outbriefform.doc)