	rine Science Outbrief - Raytheon Polar Services June 20				
PI: Domack Event#: G-096-L			Ph: 315-859-4711	Cruise #:	MPC: Lowe
			E-mail:	LMG04-04	
			∟-man.		Date: 5/11/04
Yes	No	Planning			Date: 0/11/04
162		Flatining			
		SIP process adequate?	SIP was adequate, but scientists assission operational, when it may not be. This the equipment is operational.	ume the equipmen here should be an	nt listed in Polar Ice other column stating
\square		RSP helpful and timely?			
		POC responsive?	Steffi Suhr-Sliester was wonderful.		
		Medical			
		Kits sent out on time?			
\boxtimes		Questions answered?			

Event#: G-096-L			
Date: 5/11/04			
Yes	No	Travel	
		TRW available and understandable?	TRW got buried with other forms in the deployment package. It should be on top of the stack of papers.
		Ticketing completed easily?	
		Meet and assist service met requirements?	
		Equipment Availability	
		Requested equipment available?	Equipment was available, but not in the expected condition.
	\boxtimes	Damaged?	
	\boxtimes	Late?	
		ECW gear in good condition?	

t#: G	-096-L	
: 5/11	/04	
No	Lab Space	
	Adequate? (electrical needs, bench space, water, etc.)	
	Remote Sensing support needs met? (QFax, Terascan, etc.)	
	Quality of Hotel Services	
	Cabins clean and neat?	
	Linens clean and in good condition?	
	Food quality and variety was good?	
	: 5/11	Adequate? (electrical needs, bench space, water, etc.) Remote Sensing support needs met? (QFax, Terascan, etc.) Quality of Hotel Services Cabins clean and neat? Linens clean and in good condition? Food quality and variety

Event#: G-096-L			
Date: 5/11/04			
Yes	No	Personnel Issues	
		ECO?	
		RSPC?	
		Research Objectives All accomplished? If not, please explain (weather, ice, equipment, personnel).	No objectives were accomplished because of extreme ice conditions. Timing of the cruise was inappropriate for the goals of this project.

Event#: G-096-L			
Date: 5/11/04		/04	
Yes	No	Surveys Completed?	
		USAP Metrics Survey	Will send surveys once students receive LMG patches.
		GPRA Facilities Survey	
		Future Cruises If returning for another cruise, are there any additional equipment or support needs your group anticipates?	See attachment.
		Anything you would like to see changed?	See attachment.

Event#: G-096-L		-096-L	
Date: 5/11/04		/04	
Date:	5/11, No	/04 Other Issues Diving, Zodiac, E-mail support, interactions with stations, etc.	Chief scientist quarters should be as nicely furnished as the lounge and MPC office. Furniture needs to be more thoroughly secured. It would have been better if technicians were better experienced and familiar with the gear. Need to have more flexibility and be able to switch between different types of gear. For each piece of equipment selected on the SIP, there should be a person on the cruise with specific training for that item. There should be mud traps installed in the sink drains in the labs. Lighting in the dry lab can be improved. A phone should be installed in the Aquarium Room.

Event#: G-096-L

Date: 5/11/04

Additional Comments/Overflow: